

## Care and Maintenance

**CLEANING:** Clean your **SolidStepCote** treated floor, tub or other surface as needed with a mop, sponge or soft to medium nylon bristled brush using water and any mild detergent. Mopping or sponge cleaning is sufficient with **SolidStepCote** 01 or 02. A bristled brush is suggested with **SolidStepCote** 03 or 04 and with 02 in situations where there is grease, heavy dirt or soapscum on the surface.

For oily floor surfaces such as restaurant kitchens, dining or buffet areas, periodic use of a cleaner/degreaser in conjunction with the cleaning methods mentioned above is recommended for optimum safety and aesthetics.

### **WARNING!**

**DO NOT** clean **SolidStepCote** treated surfaces with highly abrasive tools such as *Scouring Pads, Motorized Rotary Cleaning Devices, Abrasive Sponges, Burnishing Devices, Steel Brushes, Diamond Pads, Sandpapers* or other *Buffing Devices*. Over abrasion will damage the surface of the coating, removing the non-slip textured aggregate and damaging the surface appearance. **DO NOT** use *Harsh Chemical Solvents* to clean as they may damage or remove the coating.

**REAPPLICATION:** Depending upon the amount of traffic where applied, **SolidStepCote** should last from one to several years before reapplication is required. In higher traffic environments, **SolidStepCote** may be reapplied locally as needed. Refer to our Application page for details.

**REMOVAL:** May be removed with the use of **EcoKleanz**, a *vegetable-based solvent*. Most standard chemical solvents will not work on **SolidStepCote**.

**STORAGE:** A water-based solution, **SolidStepCote** should be stored in above freezing temperatures. Recommended storage temperatures range from 50 to <80 degrees Fahrenheit.